

finder Cross Reference Guide by Series



| Finder | 30 Series | 34 Series | 36 Series | 38 Series | 40 Series | 41 Series | 43 Series | 55 Series | 56 Series | 60 Series | 62 Series |
|------------------|----------------|-----------|-----------|-----------|--|----------------------------------|----------------|-------------------------------------|------------------------|----------------------|------------------|
| Allen-Bradley | | 700-TBR | | 700-HL | 700-HP | | | 700-HC | 700-HF | 700-HA | 700-HB 700-HD |
| American Zettler | AZ820 AZ830 | | AZ941 | | AZ690 AZ692 AZ725 AZ735 | AZ742 AZ762 AZ763 AZ764 | AZ696 | AZ140 | AZ1309 | AZ1010 | |
| Aromat | DS2E DS2Y | APE | JS | | JW JR | | | HC2 HC3 HC4 | HL2 | | HP32 HP33 |
| Carlo Gavazzi | | | | | MZF MZP | | M15EB M15ED | RMI | | RF11 RF80 | |
| Cutler Hammer | | | | | | | | D2PR | D7PR2 D7PR4 | D3PR | D5PR |
| Deltrol | | | | | | | | 320 | 310 | 201 | 203 |
| Eagle Signal | | | | | | | | 17P4 | | 22Q | 30E |
| Eichhoff | E230 | | | | E3201 E3206 E3208 | | E3207 E3242 | | | | |
| Elesta | | | | | SGR | | SVR | | | SKR | |
| Feme | | | | | MZF MZP | M15MB | M15EB M15ED | | | RCP | |
| Fujitsu | FBR240 | | FBR160 | | FBR610 FBR620 | | JS | FRL263/02 FRL263/03 FRL263/04 | FRL263/02 FRL263/04 | | FRL251 FRL253 |
| Furnas | | | | | | | | 46PD | 46PC | 46PA | 46B 46PB |
| Guardian | 1495 | | 1725 | | 1625 1655 1665 | | | 1310 1315 | 1390 1395 | 1210 1410 1415 | 1510 1515 |
| Hasco | HAS HS | | KLT | | PR | | | | UJ | | |
| IDEC | RD2N RW22 | | RCN1V | | | | | RY4S RU2S RU4S RM2 | RH2B RH4B | RR2P RR3P | RR2B RR3B |
| Kuhnke | RE2L RG2L | | | | 107G1 107G2 107P1 109G1 109G2 109P1 | 171G1 171G2 171P1 | | 111A4 111G4 | | UF2 UF3 RS | UB2 UB3 RS |

Please validate cross by reviewing detailed technical specifications found in the Finder catalog.

9/17/2004 (IK)

finder Cross Reference Guide by Series



| Finder | 30 Series | 34 Series | 36 Series | 38 Series | 40 Series | 41 Series | 43 Series | 55 Series | 56 Series | 60 Series | 62 Series |
|----------------|------------------|-----------|-------------------|-----------|------------------|--------------|-----------|-------------------|-----------------------|----------------------|------------------|
| Magnecraft | | | W178 | | W76 | W76 | | W78 782 | W78AR W78RC 782 | W250 750 | W388 |
| Midtex | 190 | | 296 | | 409 | | | 156 | 258 | 155 158 | 157 |
| NTE | R40 | | R46 | | R22 R25 | | | R12 | R14 | R02 | R10 |
| Omron | G2V G5V2 | | G5LE | | G2R | G2RL | G6RN | MY2 MY3 MY4 | LY2 LY4 | MK2P MK3P | MJ2P MJ3P |
| P&B / Tyco | V23105 | | T7C T7N T70 | | RKA RKS | RT | T75 | KHU KHAU | K10P | KRPA | KUP |
| Phoenix | | REL-MR | | PLC-RSC | REL-KSR | REL-MR | | | | | |
| Relpol | | | | | RM82 RM83 | RM84 RM85 | RM96 | R4 | | R15 | |
| Schrack | RS | | TN ZF | | RP | RT | RY | RA ZG ZT | TM | MT MR MZ RL | RM |
| Siemens | V23105 V23024 | V23092 | V23082 | | V23037 V23056 | | V23061 | V23100-V7 | | V23100-V9 | |
| Sky | SKG | | CKC | | SKE | | | SKMP | SKNP | SKKP | SKAP |
| Song Chuan | | | 801H | | 793 | 845 | | SCLB SCLD | SCL SCLA | 703 | 731 |
| Square D | | | | | | | | 8501RS | 8501RS | 8501KP | 8501KF 8501KU |
| Struthers-Dunn | 272 | | 270 | | 277 | | | C281 | C281 | A314 | A283 |
| Takamisawa | | | | | VS | | JS | | | | |
| Turck/Releco | | | | | | | | C9 | C7 | C2 C3 | C5 |

For assistance, alternative crosses and items not listed, please feel free to call us at 770-271-4431.

FINDER RELAYS, INC.

4465 Commerce Drive, Suite 103
Buford, GA 30518

Phone: **770-271-4431**

Fax: **770-271-7530**

For details on Relays, Timers and Sockets, please visit our Website at

www.findernet.com

Please validate cross by reviewing detailed technical specifications found in the Finder catalog.

9/17/2004 (IK)